

This report provided free of charge by:

Dream Auto Collection Inc 3837 Pembroke Rd Hollywood, FL 33021

877-589-7935

CARFAX History-Based Value Report



	Vehicle History Report [™] US \$4					
2011 MERCEDES-BENZ M-CLASS ML 63 AMG	No accidents or damage reported to CARFAX					
VIN: 4JGBB7HBXBA679981 4 DOOR WAGON/SPORT UTILITY 6.2L V8 F DOHC 32V GASOLINE ALL WHEEL DRIVE	27 Service history records					
	At least 1 open recall					
	2 Previous owners					
This CARFAX Report Provided	Personal vehicle					
^{by:} Dream Auto Collection Inc	00월 124,378 Last reported odometer reading					

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 8/22/23 at 6:02:15 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX.

Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2011	2013
Type of owner	Personal	Personal
Estimated length of ownership	2 yrs. 3 mo.	9 yrs. 1 mo.
Owned in the following states/provinces	Utah	Connecticut
Estimated miles driven per year	10,692/yr	10,605/yr
Last reported odometer reading	20,229	124,378

CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem	Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem

CARFAX Reality **GUARANTEED** - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. View Terms | View Certificate

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	No Issues Reported	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported	No Issues Reported
Manufacturer Recall	No Recalls Reported	Recall Reported

At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.		
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Detailed History

Owner 1 Purchase	ed: 2011	Low mileage! This than the industry a miles per year.			Personal Vehicle 10,692 mi/y
Date	Mileage	Source		Comments	
04/02/2011	15	Utah Motor Vehicle Dept.		Vehicle purchase - Titled or registere	reported ed as personal vehicle
04/04/2011	120	Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com	×	Vehicle serviced	
05/09/2011		Utah Motor Vehicle Dept. Draper, UT Title #UT10900522		Title issued or up - First owner repor - Loan or lien repor	ted
05/10/2011	1,183	Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com	×	Vehicle serviced	
08/03/2011	5,901	Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com	×	Vehicle serviced - Tires rotated	
08/16/2011	6,244	Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com	×	Vehicle serviced	
11/19/2011	8,564	Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com	×	Vehicle serviced	
04/10/2012		Utah Motor Vehicle Dept. Draper, UT Title #UT10900522		Registration issue - Loan or lien repor - Passed safety ins	rted

13,619	Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com		Vehicle serviced - Maintenance inspection completed - CV boot(s) replaced - Axle(s) replaced - Front wheel bearing(s)/hub(s) replaced - Front axle(s) replaced/repaired
	Utah Motor Vehicle Dept. Draper, UT Title #UT12056894		Title issued or updated - Correction to record - Loan or lien reported
17,594	Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com		Vehicle serviced - Maintenance inspection completed - Brake fluid flushed/changed
20,229	Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com	×	Vehicle serviced
	Utah Motor Vehicle Dept. Draper, UT Title #UT12056894		Registration issued or renewed - Correction to record - Loan or lien reported - Passed safety inspection
	Dealer Inventory		Vehicle offered for sale
	Mercedes-Benz Certified Pre-Owned Dealer Lindon, UT		Offered for sale as a Mercedes-Benz Certified Pre-Owned Vehicle
	Pre-Owned Vehicles		
d: 2013			
Mileage	Source		Comments
	Connecticut		Vehicle purchase reported
27,175	Motor Vehicle Dept.		
	17,594 20,229 d: 2013	Lindon, UT 801-222-4400 mboflindon.com Utah Motor Vehicle Dept. Draper, UT Title #UT12056894 17,594 Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com 20,229 Mercedes-Benz Of Lindon Lindon, UT 801-222-4400 mboflindon.com Utah Motor Vehicle Dept. Draper, UT Title #UT12056894 Dealer Inventory Mercedes-Benz Certified Pre-Owned Dealer Lindon, UT Mercedes-Benz Certified Pre-Owned Dealer Lindon, UT	Lindon, UT 801-222-4400 mboflindon.com Utah Motor Vehicle Dept. Draper, UT Title #UT12056894 17,594 Mercedes-Benz Of Lindon X 801-222-4400 mboflindon.com 20,229 Mercedes-Benz Of Lindon X 801-222-4400 mboflindon.com Utah Motor Vehicle Dept. Draper, UT Title #UT12056894 Dealer Inventory Mercedes-Benz Certified Pre-Owned Dealer Lindon, UT Mercedes-Benz Certified Pre-Owned Dealer Lindon, UT Mercedes-Benz Certified Pre-Owned Dealer Lindon, UT Mercedes-Benz Certified Pre-Owned Vehicles

09/03/2013	27,698	Hartford Toyota Hartford, CT 860-278-5411 hartfordtoyota.com	×	Vehicle serviced
09/06/2013		Connecticut Motor Vehicle Dept. West Hartford, CT		Registration issued or renewed - Vehicle color noted as Black
10/22/2013		Connecticut Motor Vehicle Dept. West Hartford, CT Title #034289005		Title issued or updated - New owner reported - Loan or lien reported
10/31/2013	30,384	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Maintenance inspection completed
01/31/2014	32,395	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Maintenance inspection completed - Evaporative emission system checked - Charcoal/vapor canister replaced - Vehicle washed/detailed - Wheels checked
07/28/2014	36,205	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Recommended maintenance performed - 40,000 mile service performed
10/31/2014	40,069	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Maintenance inspection completed - Tailgate lock/latch repaired

		241 Customer Favorites		
11/06/2014		Connecticut Motor Vehicle Dept. West Hartford, CT		Registration issued or renewed - Vehicle color noted as Black
11/12/2014	40,289	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Maintenance inspection completed - Door lock relay replaced - Tailgate lock/latch repaired
11/21/2014		Connecticut Motor Vehicle Dept. West Hartford, CT Title #034289005		Title or registration issued - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as Black
09/29/2015	48,824	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Maintenance inspection completed - 50,000 mile service performed
01/05/2017	63,524	Connecticut Inspection Station Hartford, CT		Passed emissions inspection
01/17/2017	63,720	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - 60,000 mile service performed - Light bulb(s) replaced
01/26/2017		Connecticut Motor Vehicle Dept. West Hartford, CT Title #034289005		Title or registration issued - Vehicle color noted as Black
11/16/2017	72,765	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m 4.4 / 5.0	×	Vehicle serviced - Maintenance inspection completed - Intake manifold gasket(s) replaced

		206 Verified Reviews 241 Customer Favorites		
11/17/2017		Prospect Foreign Car Center Inc. West Hartford, CT 860-236-6136 prospectforeigncar.net/ \$\$5.0 / 5.0 23 Verified Reviews \$\$8 Customer Favorites	×	Vehicle serviced - Brake pad sensor(s) replaced - Brakes checked - Brake pads replaced - Front brake pads replaced - Rear brake pads replaced
12/01/2017	73,135	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Maintenance inspection completed
09/25/2018	81,289	Prospect Foreign Car Center Inc. West Hartford, CT 860-236-6136 prospectforeigncar.net/ \$\$5.0 / 5.0 23 Verified Reviews \$\$38 Customer Favorites	×	Vehicle serviced - Intake manifold gasket(s) replaced - Oil and filter changed - Drivability/performance checked - Front turn signal/parking bulb(s) replaced - Engine/powertrain computer/module checked - Air filter replaced
10/30/2018	82,457	Connecticut Inspection Station Hartford, CT		Passed emissions inspection
11/28/2018		Prospect Foreign Car Center Inc. West Hartford, CT 860-236-6136 prospectforeigncar.net/ \$\scrimestriangletarrow 5.0 / 5.0 23 Verified Reviews \$\$ 38 Customer Favorites	×	Vehicle serviced - Engine oil/fluid leak checked
07/04/2019	91,412	Pep Boys W Hartford, CT 860-570-2525 pepboys.com \bigstar 4.4 / 5.0 43 Verified Reviews 112 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Tire repaired - Tire pressure monitoring system reset - Tire(s) balanced

10/15/2019	95,803	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Maintenance inspection completed - 90,000 mile service performed - Tire(s) balanced - Evaporator case drain hose serviced - Brake fluid checked - Antifreeze/coolant checked - Hood operation checked - Hood operation checked - Power steering checked - Brakes checked - Tire condition and pressure checked - Fluids checked - Oil and filter changed - Maintenance reminder reset
08/26/2020	102,619	Connecticut Inspection Station Hartford, CT		Passed emissions inspection
08/26/2020		Connecticut Motor Vehicle Dept. West Hartford, CT Title #034289005		Title or registration issued - Vehicle color noted as Black
03/23/2021		Connecticut Motor Vehicle Dept. West Hartford, CT Title #034289005		Title or registration issued - Vehicle color noted as Black
07/06/2021		Prospect Foreign Car Center Inc. West Hartford, CT 860-236-6136 prospectforeigncar.net/ 5.0 / 5.0 23 Verified Reviews 38 Customer Favorites	×	Vehicle serviced
08/05/2021	112,336	New Country Motor Cars Hartford, CT 860-278-2000 newcountrymotorcars.co m	×	Vehicle serviced - Maintenance inspection completed
11/18/2021	115,599	Valvoline Instant Oil Change West Hartford, CT 860-232-5601 vioc.com 4.7 / 5.0	×	Vehicle serviced - Oil and filter changed

232 Verified Reviews **413** Customer Favorites

05/27/2022	Mercedes-Benz USA LLC	Manufacturer Safety recall issued - NHTSA #22V315 - Recall #2022050015 Recall - Safety Title/ Topic: Brake Booster - No Brake Pedal Re-work MY: 2006-2013 Model(s): Various - Status: Remedy Available
		Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall
		 ⊖ Learn more about this recall
determined that (251 platform) v corrosion in the with significant In this case, the pedal forces rec distance.Addition particularly stro	t on certain Model Year ("MY") 2006 vehicles, the function of the brake be joint area of its housing. After exter water exposure, this corrosion migh brake force support might be reduc quired to decelerate the vehicle and, onally, in rare cases of very severe c ong or hard braking maneuver to cau	nufacturer of Mercedes-Benz vehicles, has 0-2012 ML, GL (164 platform) and R-Class ooster might be affected due to advanced nded time in the field and in conjunction ht lead to a leakage of the brake booster. ced, leading to an increase in the brake /or to potentially increased stopping forrosion, it might be possible for a use mechanical damage in the brake

booster, whereby the connection between brake pedal and brake system would fail. In such a very rare case, it would not be possible to decelerate the vehicle via the service brake. Thus, the risk of a crash or injury would be increased. The function of the foot parking brake is not affected by this issue. An authorized Mercedes-Benz dealer will remove the rubber sleeve, check the brake booster on the affected vehicles and - depending on the result of this inspection - replace as necessary.

After extended time in the field and in conjunction with significant water exposure, this corrosion might lead to a leakage of the brake booster. In this case, the brake force support might be reduced, leading to an increase in the brake pedal forces required to decelerate the vehicle and/or to potentially increased stopping distance. Additionally, in rare cases of very severe corrosion, it might be possible for a particularly strong or hard braking maneuver to cause mechanical damage in the brake booster, whereby the connection between brake pedal and brake system would fail. In such a very rare case, it would not be possible to decelerate the vehicle via the service brake. Thus, the risk of a crash or injury would be increased. The function of the foot parking brake is not affected by this issue.

Remedy: An authorized Mercedes-Benz dealer will remove the rubber sleeve, check the brake booster on the affected vehicles and - depending on the result of this inspection - replace as necessary.

10/17/2022 124,371 Auto Auction



Millions of used vehicles are bought and sold at auction every year.



Brooklyn, NY 646-256-4246 bestcarncare.com/



33 Verified Reviews

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.



facebook.com/CARFAX



C About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved. 8/22/23 6:02:15 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2011 MERCEDES-BENZ M-CLASS vehicle (VIN: 4JGBB7HBXBA679981), which is based on information supplied to CARFAX and available as of 8/22/23 at 7:02 PM (EDT).

Customer Signature

Date

y

Dealer Signature

Date

Ϊ